

# Assembly sets

Pos.	St.	Benennung	EDV-Nummer	Preis
<b>1</b>		<b>Montagesatz VNG 701</b>	<b>321.101.705.000</b>	<b>on inquires</b>
1	1	delay cone 12	321.101.005.016	
2	1	expansion sleeve	321.101.005.002	
3	1	stepseal-receiver 12, upper	321.101.005.007	
4	1	stepseal-receiver 12, down	321.101.005.008	
5	1	leading-in sleeve 11,7	321.101.005.020	
6	1	circlip pliers 12	321.101.005.021	
7	1	calibrating piston 12	321.101.005.011	
8	1	repair device	321.101.005.004	
9	1	Valve key 5	321.801.000.091	
10	1	Valve key 6	321.801.000.090	

Pos.	St.	Benennung	EDV-Nummer	Preis
<b>1</b>		<b>Montagesatz VNG 801</b>	<b>321.801.105.000</b>	<b>on inquires</b>
1	1	delay cone 12	321.101.005.016	
2	1	expansion sleeve	321.101.005.002	
3	1	stepseal-receiver 12, upper	321.101.005.007	
4	1	stepseal-receiver 12, down	321.101.005.026	
5	1	leading-in sleeve 11,7	321.101.005.020	
6	1	circlip pliers 12	321.101.005.021	
7	1	calibrating piston 12	321.101.005.027	
8	1	repair device	321.101.005.004	
9	1	Valve key 5	321.801.000.091	
10	1	Valve key 6	321.801.000.090	

Pos.	St.	Benennung	EDV-Nummer	Preis
<b>1</b>		<b>Montagesatz VNG 802</b>	<b>321.802.105.000</b>	<b>on inquires</b>
1	1	delay cone 12	321.101.005.016	
2	1	expansion sleeve	321.101.005.002	
3	1	stepseal-receiver 12, upper	321.101.005.007	
4	1	stepseal-receiver 12, down	321.101.005.026	
5	1	leading-in sleeve 11,7	321.101.005.020	
6	1	circlip pliers 12	321.101.005.021	
7	1	calibrating piston 12	321.101.005.027	
8	1	repair device	321.101.005.004	
9	1	Valve key / release staff	321.802.000.090	
10	1	Valve key / Steering round piston 1	321.802.000.091	
11	1	Valve key / Steering round piston 2	321.802.000.092	